



10. 2003 NE - GIS:

Staging area for hotlanes construction prior to I-495 widening and realignment of off ramp. Note approximate new location of off ramp.

11. 2009 - GIS:

CONCERN:

Note impact of staging area at height of construction.

12. 2015 - GIS:

CONCERN:

Note impact of staging area even after equipment has been largely removed.



13. 2016 - Google Aerial:

CONCERN:

A. Note area of impervious surface years after staging area is closed.

SUGGESTIONS:

B. Due to the overhead transmission lines this area cannot be reforested however the vegetation should be returned to a high quality meadow for the entire area of impact.

C. This should include deep tilling of soil and planting with an approved native meadow seed mix.

D. Warranty of restoration work should continue until native vegetation is thoroughly established throughout the Limit of Disturbance.

