

Lake Accotink Farm Pond Repairs late 2025



August 7, 2025 Excavating the slope



August 7, 2025 Earthen ramp needed for excavating equipment access



October 10, 2025 Laying the new pipe
Vertical steel sheets stabilize the slope



November 29, 2025 Final grade achieved

Unlike earlier attempted repairs, this looks stable. The pond has been cleared where it had been filled in by the sediment from the gully on the slope.



November 29, 2025 Mud excavated from the northern end of pond



November 29, 2025 Southern end of pond reconnected